

Quillmere Instruments

K2 Field Meter: warranty and returns

Warranty

The K2 field meter carries a warranty of 24 months from the date of delivery. The warranty covers the sensor head, the display and the charging circuit. It does not cover the battery, which is a consumable part.

Returns

Unused units may be returned within 30 days of delivery for a full refund. The unit must be in its original packaging with all accessories. Opened units are refunded less a 15 percent restocking fee.