

K2 Field Meter

Technical specification

Measurement range: 0 to 2,000 ppm

Accuracy: plus or minus 2 percent of reading

Operating temperature: -10 to 50 degrees C (1)

Storage temperature: -20 to 60 degrees C

Power: USB-C, 5 V

Weight: 410 g

Ingress protection: IP54

The K2 is designed for handheld use in greenhouses, warehouses and plant rooms. Readings are logged every sample interval and kept when the unit is switched off.

(1) Units with serial numbers below K2-20000 are rated to a maximum of 40 degrees C.